



BEFORE / AFTER DOCUMENTATION

Job completion evidence package · paired pre-work and post-work aerial documentation

SAMPLE REPORT — PLEASE READ

All client names, properties, findings and figures in this document are **fictitious and shown for illustration only**. Delivered client reports are confidential and are never published. The verification code is deactivated for publication. Both flights are flown from matched altitudes and headings so the pairs line up visually, and every frame carries its original capture timestamp and GPS position.

Client	Sample Roofing Co. (fictitious)	Report ID	MWA-BA-SAMPLE-0001
Property	101 Example Way, Anytown, NC	Work order	WO-SMP-BA-01
Scope of work	Full roof replacement — architectural shingle	Issued	Sample
Capture dates	Before: day 1 · After: day 9	Remote PIC	FAA Part 107 certified

WHY THIS PACKAGE EXISTS

A before/after pair settles the two arguments that cost contractors the most money: what the roof actually looked like before you touched it, and what was delivered when you left. Both flights are flown from matched altitudes and headings so the pairs line up visually, and every frame carries its original capture timestamp and GPS position. Homeowners see the work; adjusters see the sequence; you keep the evidence.

HOW THIS REPORT IS PRODUCED — AI PLUS HUMAN

AI drafts the written report from the captured frames; a **Part 107 pilot edits and signs every line**. The pilot is the author of record, not the software.

The AI never touches the imagery. Every image is fingerprinted at capture and sealed into a signed manifest, and each report carries a QR code you or your carrier can use to verify the exact file we delivered — in a browser, no account needed.

Speed from the AI, judgement from a certified pilot, evidence provably untouched.

CAPTURE SUMMARY


Phase	Date / time	Aircraft	Frames	Altitude AGL	Status
Before — pre-work	Day 1 · 9:14 AM	DJI Mavic 3	38 photos	95 ft	COMPLETE
After — post-work	Day 9 · 9:31 AM	DJI Mavic 3	38 photos	95 ft	COMPLETE
Matched pairs delivered	—	—	12 pairs	matched	COMPLETE
Delivery	Day 9 · 4:40 PM	—	Annotated PDF + full-res set	—	SAME DAY

MATCHED PAIRS — ELEVATION INDEX


Each pair is captured from the same position and angle on both flights. Full-resolution originals accompany this report.



Before / After Documentation · MWA-BA-SAMPLE-0001 · SAMPLE



PLACEHOLDER SKETCH — stands in for the matched aerial frames. A delivered report carries the actual photographs at full resolution, annotated exactly as shown here: conditions ringed in red before the work, in green after it.



PLACEHOLDER SKETCH — second matched pair. Both flights are flown from the same altitude and heading so the frames line up when placed side by side.

#	Elevation / area	Documented before	Documented after
1	North elevation	Granule loss, 3 lifted tabs at ridge	New field shingle, ridge cap seated
2	East elevation	Two displaced shingles above gutter line	Full replacement, gutter line clear
3	Ridge line	Cap shingles weathered, exposed nail heads	New ridge cap, fasteners covered
4	Valley — south	Debris accumulation, flashing visible	Valley cleared, flashing seated
5	Penetrations	Boot cracked at plumbing stack	New boot installed and sealed
6	Site / grounds	Pre-existing landscaping condition	Grounds clear, no debris remaining

WHAT YOU RECEIVE

Deliverable	Format	Timing
Annotated before/after PDF (this document)	PDF	Same day as the post-work flight
Matched full-resolution image pairs	JPEG, original capture data intact	Same day



Deliverable	Format	Timing
Chain-of-custody manifest	Signed manifest + per-image hashes	With delivery
Secure delivery link	Password-protected — link and passcode sent separately	On release

**VERIFIED CHAIN OF CUSTODY**

On a delivered report, every image, video and report in the package is fingerprinted (SHA-256) at the mission and sealed into a signed, published manifest recording GPS position, capture time, pilot certification, aircraft and custody events. The client scans the code, or goes to mwairlift.com/verify, and drops in the file they received. It is checked in their own browser and never uploaded. A re-saved or re-compressed copy will not match.

The code on this sample has been deactivated. It resolves to nothing, deliberately — a public sample must not carry a live verification route to a client mission.

Scope. Visual aerial documentation of observable, accessible exterior conditions. Documentation and imagery only — **not a licensed home or building inspection, structural or engineering evaluation, or any certification.** MW AIRLIFT™ does not sell repairs and holds no financial interest in any repair recommendation. Not survey-grade and not a land survey; no measurements, areas or boundaries are provided (NC GS 89C).

SAMPLE
NOT A CLIENT DELIVERABLE